Occurrence #1		
Name of Driver	ANDREW GAIL LOGUE	
Date of Accident	10/29/24	
Vehicle #1	BUS #390	
Vehicle #2	2020 INFINITY QX8 SUV	
Police Report Filed:	YES	
Insurance Claim Reported	NO	
Violations Charged:	NO	
Injuries	NO	
Description	Vehicle #1 was stopped at the intersection of Nansemond Pkwy and Portsmouth Blvd, preparing to make a left turn. Vehicle #2 was directly behind Vehicle #1, and got into the right turn lane to make a right turn onto Portsmouth Blvd. The battery access panel door from Vehicle #2 popped open and struck the rear right corner of Vehicle #1, causing paint transfer to Vehicle #1. There was no damage to Vehicle #2.	
Estimate of Damages		
Vehicles #1	\$00.00	
Vehicle #2	\$200.00	

Occurrence #2		
Name of Driver	MELISSA VEALE	
Date of Accident	11/01/2024	
Vehicle #1	BUS # 425	
Vehicle #2	2015 DODGE RAM	
Police Report Filed:	YES	
Insurance Claim Reported	YES	
Violations Charged:	YES -Refused to sign Summons	
Injuries	NO	
Description	Vehicle #2 was parked on the right side of the road. When Vehicle #1 was backing up, Vehicle #1 struck the driver side rear tail light with the driver side rear bumper of Vehicle #1. Both Vehicle #1 and #2 sustained minor rear bumper damage. No injuries reported	
Estimate of Damages		
Vehicles #1	\$500.00	
Vehicle #2	\$500.00	

Occurrence #3		
Name of Driver	FREDDIE J. DAVIS	
Date of Accident	11/01/2024	
Vehicle #1	2011 DODGE SUV	
Vehicle #2	WHITE FLEET 5011 VAN	
Police Report Filed:	YES	
Insurance Claim Reported	YES	
Violations Charged:	NO	
Injuries	NO	
Description	Vehicle #1 and Vehicle #2 were traveling in the 5400-BLK of the Nansemond Pkwy. Vehicle #1 was changing lanes when it struck Vehicle #2 on the left rear side. Vehicle #1 sustained damage on the front right side. Vehicle #2 sustained damage to the left right side.	
Estimate of Damages		
Vehicle #1	\$1000.00	
Vehicle #2	\$1000.00	

Occurrence #4		
Name of Driver	JUANA HERREA	
Date of Accident	11/04/2024	
Vehicle #1	BUS #208	
Vehicle #2	2022 CHEVY 2500 PICKUP TRUCK	
Police Report Filed:	YES	
Insurance Claim Reported	NO	
Violations Charged:	NO	
Injuries	NO	
Description	Vehicle # 1 and vehicle #2 were both wide and bumped mirrors causing minor paint transfer and scuffing.	
Estimate of Damages		
Vehicles #1	\$10.00	
Vehicle #2	\$75.00	

Occurrence #5		
Name of Driver	RACHEL COPELAND	
Date of Accident	11/08/2024	
Vehicle #1	BUS #497	
Vehicle #2		
Police Report Filed:	NO	
Insurance Claim Reported	NO	
Violations Charged:	NO	
Injuries	NO	
Description	Vehicle #1 was traveling down Wedgewood Road when a deer ran out of the woods and collided into the passenger side front bumper of the Bus. There was damage to the front bumper & bottom of the hood. And there was a small crack in the passenger side headlight.	
Estimate of Damages		
Vehicles #1	\$200.00	
Vehicle #2	\$00.00	