

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
September 30, 2021**

<u>Occurrence #1</u>	
Name of Driver	BROWN, KAREN
Date of Accident	09/04/20120
Vehicle #1	1988 FORD DUMP TRUCK
Vehicle #2	BUS # 7
Police Report Filed:	Yes
Insurance Claim Reported	Yes
Violations Charged:	Yes
Injuries	Yes - Driver Karen Brown had some
Description	Vehicle #1 was traveling westbound on Wilroy Rd. and Vehicle #2 was traveling eastbound on Wilroy Rd.. Vehicle #1 sustained damage to the front bumper and driver side tire. Vehicle #2's driver side mirror, rear driver side tire and left quarter panel were damaged. . Camera footage was taken from Vehicle #2, and which showed that Vehicle #1 struck Vehicle #2 while they were braking.
Estimate of Damages	
Vehicles #1	\$7000.00
Vehicle #2	\$5000.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
September 30, 2021**

<u>Occurrence #2</u>	
Name of Driver	WOODS, MICHELLE
Date of Accident	09/07/2021
Vehicle #1	BUS # 44
Vehicle #2	2013 NISSAN
Police Report Filed:	NO
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	Vehicle # 1 was traveling on Nottingham Dr to Archer Dr. Vehicle # 1 pulled off before the crossing arm had fully retracted. Vehicle #1 crossing arm hit the parked Vehicle #2. Vehicle #1 crossing arm was broken off. Vehicle #2 sustained a scratch and a small dent to the driver side rear fender.
Estimate of Damages	
Vehicles #1	\$100.00
Vehicle #2	\$500.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
September 30, 2021**

<u>Occurrence #3</u>	
Name of Driver	WOODS, MICHELLE
Date of Accident	09/07/2021
Vehicle #1	BUS # 44
Vehicle #2	N/A
Police Report Filed:	NO
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	Vehicle # 1 was traveling around the YMCA parking lot.. Vehicle #1 crossing arm had not fully retracted and hit a stationary object and was broken off.
Estimate of Damages	
Vehicles #1	\$20.00
Vehicle #2	N/A