

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #1</u>	
Name of Driver	MONTREAL SCOTT
Date of Accident	04/23/2024
Vehicle #1	BUS #477
Vehicle #2	N/A
Police Report Filed:	NO
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	Vehicle #1 mirror was broken and the driver does not know how or when it happened. The mirror was discovered on 04/23/2024 after coming back from a field trip in Norfolk, VA
Estimate of Damages	
Vehicles #1	\$150.00
Vehicle #2	\$00.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #2</u>	
Name of Driver	JENNIFER DAVIS
Date of Accident	04/24/2024
Vehicle #1	BUS 412
Vehicle #2	BACKED IN THE A DITCH
Police Report Filed:	YES
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	<p>On April 24, 2024, around 4:31 PM, vehicle #1 crash occurred at 2416 Longstreet Ln. Vehicle #1 was traveling southbound in the 2400-BLK of Longstreet Ln when it began reversing to complete a turnaround. While reversing, vehicle one went off the roadway into a ditch. Vehicle #1 sustained minor damage to its left rear tire.</p> <p>Driver of vehicle#1 and 1 student sustained no injuries.</p>
Estimate of Damages	
Vehicles #1	\$300.00
Vehicle #2	\$300.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #3</u>	
Name of Driver	VERNICE MCMILLAN
Date of Accident	04/25/2023
Vehicle #1	BUS #426
Vehicle #2	2019 TOYOTA SUV
Police Report Filed:	YES
Insurance Claim Reported	YES
Violations Charged:	NO
Injuries	NO
Description	On 04/25/2024 at approximately 1735 hours, Vehicle #1 was attempting to navigate the large school bus through a narrow street with vehicles parked on both sides of the road. While attempting to navigate between vehicles, the far back passenger corner of the school bus made contact with the front driver's side, just behind the headlight, of an unoccupied, parked Vehicle #2. There were no injuries to anyone on the bus, and the only damage to the bus, Vehicle #1, was a broken reflector. The only damage to Vehicle #2, which was unoccupied, there were some minor paint scratches just behind the headlight on the driver's side.
Estimate of Damages	
Vehicles #1	\$10.00
Vehicle #2	\$50.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #4</u>	
Name of Driver	NIKKI LEIGH BLAIR
Date of Accident	04/29/2024
Vehicle #1	BUS # 409
Vehicle #2	2018 FORD F250
Police Report Filed:	YES
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	<p>Vehicle 1 (School bus) was traveling eastbound in the 5500-blk of Everets Rd. Vehicle 2 (pickup) was traveling westbound in the 5500-blk of Everets Rd. Vehicles met on a curve and hit mirrors. Unknown which, if any, vehicle crossed the double yellow center lane marking. One passenger in Vehicle 1 was complaining of knee pain after hitting the seat in front of her and falling to the floor.</p> <p>Vehicle1: Driver side mirror damage and scratches down driver side Vehicle 2: Driver side mirror damage and driver door window damage.</p>
Estimate of Damages	
Vehicle #1	\$500.00
Vehicle #2	\$500.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #5</u>	
Name of Driver	VILMA GUARDIOLA
Date of Accident	05/10/2024
Vehicle #1	BUS #414
Vehicle #2	BUS #415
Police Report Filed:	NO
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	Vehicle #1 was entering FBES parking lot from Nansemond Parkway and turned too short and made contact with Vehicle # 2 driver side crossover mirror. There was minimal damage to each bus's mirror.
Estimate of Damages	
Vehicles #1	\$0.00
Vehicle #2	\$0.00

**SUFFOLK PUBLIC SCHOOLS
TRANSPORTATION ACCIDENT REPORT
MAY 31, 2024**

<u>Occurrence #6</u>	
Name of Driver	ALICE HUNT
Date of Vandalism	05/10/2024
Vehicle #1	BUS #415
Vehicle #2	BUS # 414
Police Report Filed:	NO
Insurance Claim Reported	NO
Violations Charged:	NO
Injuries	NO
Description	Vehicle #1 was sitting at the stop sign at the entrance of FBES parking lot. Vehicle # 2 turned too short as she entered FBES parking lot from Nansemond Parkway. Vehicle #2 made contact with Vehicle #1 driver side crossover mirror. There was minimal damage to each bus's mirror.
Estimate of Damages	
Vehicles #1	\$0.00
Vehicle #2	\$0.00